

claim converted to BLM lease

1/27/03

FORM MR-AR
(Revised 2/2001)

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

RECEIVED

JAN 22 2003

DIV. OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 01/01/02 To (mo./yr.) 12/31/02
2. DOGM File Number (Mine No): 51211032
3. Mine Name: Phyllite #1
- * 4. Mineral(s) Mined (or permitted to mine): Decorative Stone (crushed)
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, SW 1/4, SE 1/4, Section 35, Township 35S, Range 17W
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: Color Country Rock, LLC
8. Permanent Street Address: 291 E 1400 S. Ste #1
City, State, Zip: St. George, UT 84790
Phone: (435) 652-1885 Fax: (435) 656-5640
9. Company Representative (or designated operator):
Name: Preston L. Hafen
Title: Manager, Operations
Business Address: 115 South Main
City, State, Zip: Vernal, UT 84782
Phone: (435) 574-2760 Fax: (435) 574-2760
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 500 Tons

* claim was stopped - operation was converted to BLM lease UTA-79397-A1 for crushed stone

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
Approximately 1/2 acre was drilled & blasted &
approximately 500 tons of the broken rock was
removed
5. How much additional acreage was disturbed during the past year? 1/2 acre approx
6. How much acreage was reclaimed during the past year? None
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
None
8. What is the **total** disturbed acreage of entire project at years end? approx 1 acre
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Remove currently broken rock (approx 3000 tons)

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

N/A III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

N/A IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Title of Operator:

Signature of Operator:

Date:

Preston L. Hefen

Manager, Operations

Preston L. Hefen

01/13/03